# General Environmental Incident Summary

Incident: 3362 Date/Time Notice: 6/23/2014 1240 DEM Incident No:

Responsible Party: MINOT AIR FORCE BASE

Date Incident: 6/21/2014 Time Incident: 1700 Duration:

County: Mountrail Twp: 151 Rng: 89 Sec: 23 Qtr: NE NW NW

Lat: 47.89020 Long: -102.04060 Method: Navigation quality GPS

Location Description: 4.5 miles SSE of Parshall.

Submitted By: DANNY KLUCK Affiliation: EMPLOYEE

Address: 5 CES/CEIE

445 PEACEKEEPER

City: MINOT AFB State: ND Zip: 58705

Received By:

Contact Person: DANNY KLUCK

5TH BOMB WING 201 SUMMIT DRIVE MINOT AFB, ND 58705

Distance Nearest Occupied Building: 0 Feet Release Contained: Yes

Type of Incident: Tank Leak

Description of Released Contaminant: DF-2 Diesel Fuel

Volume Spilled:1200.00 gallonsAg Related:NoEPA Extremely Hazardous Substance:NoReported to NRC:Yes

Cause of Incident:

A FUEL FILTER MALFUNCTIONED LEAKING APPROXIMATELY 1200 GALLONS OF DF-2 DIESEL FUEL IN A LAUNCH SUPPORT BUILDING AT LAUNCH FACILITY H-5.

Risk Evaluation:

**NONE** 

# of Fatalities: 0 # of Injuries: 0 Affected Medium: 01 - air

Potential Environmental Impacts:

NONE

Action Taken or Planned:

THE ON-SITE TEAM STOPPED THE LEAK AND CONTAINED THE SPILL TO THE LAUNCH SUPPORT FACILITY. NO FUEL REACHED NEARBY SOIL OR WATER. A VACUUM TRUCK RECOVERED THE FUEL LATER THAT DAY FOR RECLAMATION AND REUSE.

Wastes Disposal Location: THE RECLAIMED FUEL WILL BE REUSED.

Agencies Involved: USAF

Monday, July 21, 2014 Page 1 of 2

## **Updates**

Date: 6/23/2014 Status: Assigned to WM Staff: Roberts, Kris

### **Updated Volume:**

#### Notes:

Release of diesel fuel from a malfunctioning fuel filter leak. Followup is necessary to confirm recovery and cleanup.

The corrective action for this incident is satisfactory.

Date: 7/2/2014 Status: Reviewed; No Followup Required Staff: Disney, Robert

## **Updated Volume:**

#### Notes:

The corrective action for this incident is satisfactory, as described in the original report.

Monday, July 21, 2014 Page 2 of 2